



TRIPLE TREE FORK INSTALLATION GUIDELINE

(Professional assembly assistance is recommended)



1) O Ring



2) Barring facing up



3) Insert O ring then Barring facing up on to fork



4) Insert fork into center tube



5) 2nd barring facing up



6) Insert on top of fork



7) large ring (a)



8) ring with slit (b)



9) Put (a) and (b) together



10) Insert (a) and (b) together on fork



11) next you will need two spacers.



12) and last O ring.



13) insert 2 spacers than last O ring



14) insert large cap over fork use a soft hammer if need.



15) Insert stem and handle bar than insert the final cap with bolt tighten.

